



Инструкция по сборке СПР Стол промышленный металлический



1x



1x



1x



1x



1x



1x




2x




6x 2x10 	12x 10x20 	10x 4x55 	4x 6x50 	12x M10
4x 	8x 	8x 40x40 	1x 	4x M6


1




2




3




4




5



6



7



ESD